

1	2	3	4	5	6	7	8	9	10	11
1	2	3	4	5	6	7	8	9	10	11
H	0-7	N-13	L-11	L-15	11-12	N-11	[	]	(	)
L-13	0-13	B-7	L-9	C-7	B-7	F-11	cc	F-7	11-7	
5	6	7	8	9	10	11	E-1	B-11	?	!
£	Q	W	E	R	T	Y	U	I	O	P
A	A	S	D	F	G	H	J	K	L	&
ff	Z	X	C	V	B	N	M	-	:	;
0.5	1	2	3	4	5	6	7	8	9	0
fi	q	w	e	r	r	y	u	i	o	p
ff	a	s	d	f	g	h	j	k	l	
ff	z	x	c	v	b	n	m	,	.	
◇	◇	◇	◇	◇	◇	◇	◇	◇	◇	◇

-2 units

+10 units

=10 units

Point	16	Face	270	Picas	Stop	L. Bars	R. Bars
Mold	16	Set	13 1/2	Points	486		
CHANGE		LEADERS—Period		Fine Dot		Hyphen	
Under pin Cap W = B1							

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O
1	6	H	Space	!						i	l	j	.	s	◇
2						:	:	-	r						◇
3	(F)	)	Ⓜ							s	t	I	J	Ⓜ	◇
4						z	a	c	e						◇
5	3	4	5	1	2					6	7	8	9	0	◇
6						L	P	ff	fi						◇
7	q	u	p	x	y					n	h	d	k	S	F
8						o	g	b	v						◇
9	R	Ⓜ	T	?		F	ae	Ⓜ	E		B		Z		◇
10															◇
11	K		A	Y						ae	G	dt	C	n	V
12						G	w	a	H						◇
13	ff	W		ff						D	g	X			◇
14						M									◇
15	N		O	Qu						m	L	U	Q	R	◇

A-10 units

Cap W 13/3 with 3-unit space (5 units)

A-18. O-19 units